VISY
FOR A BETTER WORLD

Visy Pulp and Paper Tumut CEMS - Correction Log

16/11/2026

Reporting Period: 1/10/2026 - 1/11/2026 **Environment Protection Licence No:** 10232

Main Stack 1

Monitoring Location No: 1
Monitoring Type Continuous
Sample Type: Air
Description: Exit point from Stack 1 to atmosphere

Opacity		**Period:** 6 Minutes	**Limit:** 20.00 %		
Start Time	End Time	Cause	Operational State	Explanation	Max Reading
02/10/26 08:18	02/10/26 08:24	Auto Zero Span Verification	Normal (Steady State)	Auto Calibration	20.64
03/10/26 08:18	03/10/26 08:24	Auto Zero Span Verification	Normal (Steady State)	Auto Calibration	20.95
04/10/26 09:18	04/10/26 09:24	Auto Zero Span Verification	Normal (Steady State)	Auto Calibration	20.90
05/10/26 09:18	05/10/26 09:24	Auto Zero Span Verification	Normal (Steady State)	Auto Calibration	20.90
06/10/26 09:18	06/10/26 09:24	Auto Zero Span Verification	Normal (Steady State)	Auto Calibration	21.32
07/10/26 09:18	07/10/26 09:24	Auto Zero Span Verification	Normal (Steady State)	Auto Calibration	21.51
08/10/26 09:18	08/10/26 09:24	Auto Zero Span Verification	Normal (Steady State)	Auto Calibration	21.64
09/10/26 09:18	09/10/26 09:24	Auto Zero Span Verification	Normal (Steady State)	Auto Calibration	22.64
10/10/26 09:18	10/10/26 09:24	Auto Zero Span Verification	Normal (Steady State)	Auto Calibration	23.23
11/10/26 09:18	11/10/26 09:24	Auto Zero Span Verification	Normal (Steady State)	Auto Calibration	22.90
12/10/26 09:18	12/10/26 09:30	Auto Zero Span Verification	Normal (Steady State)	Auto Calibration	34.87
13/10/26 09:18	13/10/26 09:30	Lime Kiln A	Lime Kiln A Scheduled Start-up/Shut-down	MSD 26 shut, running out product and rubble for maintenance access	32.72
13/10/26 22:48	13/10/26 22:54	Auto Zero Span Verification	Normal (Steady State)	Auto Calibration	31.17
14/10/26 09:18	14/10/26 09:24	Auto Zero Span Verification	Normal (Steady State)	Auto Calibration	20.29
17/10/26 19:00	17/10/26 19:06	Auto Zero Span Verification	Normal (Steady State)	Auto Calibration	21.87
17/10/26 19:24	17/10/26 19:30	Power Boiler	Power Boiler Scheduled Start-up/Shut-down	Power Boiler Starting up after MSD26	59.45
18/10/26 09:18	18/10/26 09:24	Auto Zero Span Verification	Normal (Steady State)	Auto Calibration	20.12

19/10/26 22:00	19/10/26 22:18	Auto Zero Span Verification	Normal (Steady State)	Auto Calibration	37.49
19/10/26 22:24	19/10/26 22:30	Auto Zero Span Verification	Normal (Steady State)	Auto Calibration	54.47
19/10/26 22:42	19/10/26 22:48	Power Boiler	Power Boiler Scheduled Start-up/Shut-down	Power Boiler Starting up after MSD26	25.94
19/10/26 23:48	19/10/26 23:54	Power Boiler	Power Boiler Scheduled Start-up/Shut-down	Power Boiler Starting up after MSD26	23.65
20/10/26 07:12	20/10/26 07:18	Auto Zero Span Verification	Normal (Steady State)	Auto Calibration	40.10
22/10/26 09:18	22/10/26 09:24	Power Boiler	Power Boiler Scheduled Start-up/Shut-down	Fuel chute blocked causing upsets and opacity	34.65
26/10/26 09:12	26/10/26 09:18	Auto Zero Span Verification	Normal (Steady State)	Auto Calibration	20.27
27/10/26 09:12	27/10/26 09:18	Auto Zero Span Verification	Normal (Steady State)	Auto Calibration	20.40
27/10/26 23:12	27/10/26 23:18	Auto Zero Span Verification	Normal (Steady State)	Auto Calibration	41.54
28/10/26 09:12	28/10/26 09:18	Auto Zero Span Verification	Normal (Steady State)	Auto Calibration	20.30
29/10/26 09:12	29/10/26 09:18	Auto Zero Span Verification	Normal (Steady State)	Auto Calibration	20.43
30/10/26 09:12	30/10/26 09:18	Auto Zero Span Verification	Normal (Steady State)	Auto Calibration	20.34
31/10/26 09:12	31/10/26 09:18	Auto Zero Span Verification	Normal (Steady State)	Auto Calibration	20.59

Authorised By:

Uday Bhagwat
Pulp Mill Manager

Johan Stoltz
General Manager