![VISY FOR A BETTER WORLD]

Main Stack 1

Monitoring Location No:	1
Monitoring Type	Continuous
Sample Type:	Air
Description:	Exit point from Stack 1 to atmosphere

Opacity		**Period:** 6 Minutes	**Limit:** 20.00 %		
Start Time	**End Time**	**Cause**	**Operational State**	**Explanation**	**Max Reading**
02/12/25 12:54	02/12/25 13:00	Auto Zero Span Verification	Normal (Steady State)	Auto Calibration	20.61
03/12/25 12:54	03/12/25 13:00	Auto Zero Span Verification	Normal (Steady State)	Auto Calibration	20.90
04/12/25 12:54	04/12/25 13:00	Auto Zero Span Verification	Normal (Steady State)	Auto Calibration	21.02
05/12/25 12:54	05/12/25 13:00	Auto Zero Span Verification	Normal (Steady State)	Auto Calibration	20.71
06/12/25 12:54	06/12/25 13:00	Auto Zero Span Verification	Normal (Steady State)	Auto Calibration	20.87
06/12/25 17:48	06/12/25 17:54	Instrument Error	Equipment Issue/Failure	Airline came off on Flue gas flow Transmitter tripping the Lime Kiln	22.67
07/12/25 12:54	07/12/25 13:00	Auto Zero Span Verification	Normal (Steady State)	Auto Calibration	21.09
08/12/25 12:54	08/12/25 13:00	Auto Zero Span Verification	Normal (Steady State)	Auto Calibration	21.43
09/12/25 12:54	09/12/25 13:00	Auto Zero Span Verification	Normal (Steady State)	Auto Calibration	21.51
09/12/25 15:24	09/12/25 15:30	Lime Kiln A ESP	Equipment Issue/Failure	Shear pin broke on Ash drag chain conveyor tripping the Kiln the pin was replaced and Kiln started, during the Purge cycle the opacity was exceeded.	29.75
10/12/25 12:54	10/12/25 13:00	Auto Zero Span Verification	Normal (Steady State)	Auto Calibration	21.65
11/12/25 12:54	11/12/25 13:00	Auto Zero Span Verification	Normal (Steady State)	Auto Calibration	21.47
12/12/25 12:54	12/12/25 13:00	Auto Zero Span Verification	Normal (Steady State)	Auto Calibration	21.16
13/12/25 12:54	13/12/25 13:00	Auto Zero Span Verification	Normal (Steady State)	Auto Calibration	21.62
14/12/25 12:54	14/12/25 13:00	Auto Zero Span Verification	Normal (Steady State)	Auto Calibration	22.54
15/12/25 12:54	15/12/25 13:00	Auto Zero Span Verification	Normal (Steady State)	Auto Calibration	21.31

|						
16/12/25 12:54	16/12/25 13:00	Auto Zero Span Verification	Normal (Steady State)	Auto Calibration		20.41
17/12/25 12:54	17/12/25 13:00	Auto Zero Span Verification	Normal (Steady State)	Auto Calibration		21.14
18/12/25 12:54	18/12/25 13:00	Auto Zero Span Verification	Normal (Steady State)	Auto Calibration		21.83
25/12/25 12:48	25/12/25 12:54	Auto Zero Span Verification	Normal (Steady State)	Auto Calibration		20.09
26/12/25 12:48	26/12/25 12:54	Auto Zero Span Verification	Normal (Steady State)	Auto Calibration		20.51
27/12/25 12:48	27/12/25 12:54	Auto Zero Span Verification	Normal (Steady State)	Auto Calibration		20.68
28/12/25 12:48	28/12/25 12:54	Auto Zero Span Verification	Normal (Steady State)	Auto Calibration		20.54
29/12/25 12:48	29/12/25 12:54	Auto Zero Span Verification	Normal (Steady State)	Auto Calibration		20.83
30/12/25 12:48	30/12/25 12:54	Auto Zero Span Verification	Normal (Steady State)	Auto Calibration		21.05
31/12/25 12:48	31/12/25 12:54	Auto Zero Span Verification	Normal (Steady State)	Auto Calibration		21.22

Main Stack 2

Monitoring Location No: 22
Monitoring Type   Continuous
Sample Type: Air
Description: Exit point from Stack 2 to atmosphere

TRS (as H2S)		**Period:** 60 Minutes	**Limit:** 3.60 mg/Nm3		
Start Time	End Time	Cause	Operational State	Explanation	Max Reading
15/12/25 22:00	15/12/25 23:00	Instrument Error	Normal (Steady State)	The CEMS was reported to have strange behavior and the CEMS was reset. All values back to normal.	4.50

Authorised By:

Uday Bhagwat
Pulp Mill Manager

Johan Stoltz
General Manager