

# Visy Pulp and Paper Tumut CEMS - Correction Log

11/08/2025

Reporting Period: 1/07/2025 - 1/08/2025

Environment Protection Licence No: 10232

## Main Stack 1

Monitoring Location No: 1

Monitoring Type: Continuous

Sample Type: Air

Description: Exit point from Stack 1 to atmosphere

| Opacity           |                |                             |                                           |                                                                                                                            |             |
|-------------------|----------------|-----------------------------|-------------------------------------------|----------------------------------------------------------------------------------------------------------------------------|-------------|
| Period: 6 Minutes |                | Limit: 20.00 %              |                                           |                                                                                                                            |             |
| Start Time        | End Time       | Cause                       | Operational State                         | Explanation                                                                                                                | Max Reading |
| 01/07/25 13:48    | 01/07/25 13:54 | Auto Zero Span Verification | Normal (Steady State)                     | Auto Calibration                                                                                                           | 22.29       |
| 02/07/25 13:48    | 02/07/25 13:54 | Auto Zero Span Verification | Normal (Steady State)                     | Auto Calibration                                                                                                           | 22.81       |
| 03/07/25 13:48    | 03/07/25 13:54 | Auto Zero Span Verification | Normal (Steady State)                     | Auto Calibration                                                                                                           | 23.50       |
| 04/07/25 13:48    | 04/07/25 13:54 | Auto Zero Span Verification | Normal (Steady State)                     | Auto Calibration                                                                                                           | 23.40       |
| 05/07/25 13:48    | 05/07/25 13:54 | Auto Zero Span Verification | Normal (Steady State)                     | Auto Calibration                                                                                                           | 25.52       |
| 06/07/25 13:48    | 06/07/25 13:54 | Power Boiler EP             | Equipment Issue/Failure                   | ESP Field 2 offline with a potential dead short, this causes opacity to be exceeded at times when soot blowing the boiler. | 26.12       |
| 07/07/25 13:48    | 07/07/25 13:54 | Power Boiler                | Power Boiler Scheduled Start-up/Shut-down | Power boiler cleaning of sand bed and ESP during Shut down preparing for Maintenance repairs                               | 25.32       |
| 08/07/25 13:48    | 08/07/25 13:54 | Auto Zero Span Verification | Normal (Steady State)                     | Auto Calibration                                                                                                           | 20.89       |
| 14/07/25 13:42    | 14/07/25 13:48 | Auto Zero Span Verification | Normal (Steady State)                     | Auto Calibration                                                                                                           | 20.52       |
| 15/07/25 13:42    | 15/07/25 13:48 | Auto Zero Span Verification | Normal (Steady State)                     | Auto Calibration                                                                                                           | 20.70       |
| 16/07/25 13:42    | 16/07/25 13:48 | Auto Zero Span Verification | Normal (Steady State)                     | Auto Calibration                                                                                                           | 20.76       |
| 17/07/25 13:42    | 17/07/25 13:48 | Auto Zero Span Verification | Normal (Steady State)                     | Auto Calibration                                                                                                           | 20.87       |
| 18/07/25 13:42    | 18/07/25 13:48 | Auto Zero Span Verification | Normal (Steady State)                     | Auto Calibration                                                                                                           | 20.91       |
| 19/07/25 13:42    | 19/07/25 13:48 | Auto Zero Span Verification | Normal (Steady State)                     | Auto Calibration                                                                                                           | 21.06       |
| 20/07/25 13:42    | 20/07/25 13:48 | Auto Zero Span Verification | Normal (Steady State)                     | Auto Calibration                                                                                                           | 21.37       |
| 21/07/25 13:42    | 21/07/25 13:48 | Auto Zero Span Verification | Normal (Steady State)                     | Auto Calibration                                                                                                           | 21.11       |

|                |                |                             |                       |                  |       |
|----------------|----------------|-----------------------------|-----------------------|------------------|-------|
| 22/07/25 13:42 | 22/07/25 13:48 | Auto Zero Span Verification | Normal (Steady State) | Auto Calibration | 21.56 |
| 23/07/25 13:42 | 23/07/25 13:48 | Auto Zero Span Verification | Normal (Steady State) | Auto Calibration | 21.51 |
| 24/07/25 13:42 | 24/07/25 13:48 | Auto Zero Span Verification | Normal (Steady State) | Auto Calibration | 21.98 |
| 25/07/25 13:42 | 25/07/25 13:48 | Auto Zero Span Verification | Normal (Steady State) | Auto Calibration | 21.67 |
| 26/07/25 13:42 | 26/07/25 13:48 | Auto Zero Span Verification | Normal (Steady State) | Auto Calibration | 22.54 |
| 27/07/25 13:42 | 27/07/25 13:48 | Auto Zero Span Verification | Normal (Steady State) | Auto Calibration | 22.29 |
| 28/07/25 13:42 | 28/07/25 13:48 | Auto Zero Span Verification | Normal (Steady State) | Auto Calibration | 22.92 |
| 29/07/25 13:42 | 29/07/25 13:48 | Auto Zero Span Verification | Normal (Steady State) | Auto Calibration | 22.70 |
| 30/07/25 13:42 | 30/07/25 13:48 | Auto Zero Span Verification | Normal (Steady State) | Auto Calibration | 23.03 |
| 31/07/25 13:42 | 31/07/25 13:48 | Auto Zero Span Verification | Normal (Steady State) | Auto Calibration | 20.37 |

## Power Boiler

**Monitoring Location No:** 3  
**Monitoring Type** Continuous  
**Sample Type:** Air  
**Description:** Discharge duct downstream of Power Boiler prior to junction with Stack 1

| Carbon Monoxide (CO) |                | Period: 60 Minutes | Limit: 140.00 mg/Nm3                      |                                                                              |             |
|----------------------|----------------|--------------------|-------------------------------------------|------------------------------------------------------------------------------|-------------|
| Start Time           | End Time       | Cause              | Operational State                         | Explanation                                                                  | Max Reading |
| 08/07/25 07:00       | 08/07/25 08:00 | Instrument Error   | Power Boiler Scheduled Start-up/Shut-down | Power Boiler offline for shut work in the ESP - indicating incorrect reading | 169.71      |

Authorised By:

**Uday Bhagwat**  
 Pulp Mill Manager



**Johan Stoltz**  
 General Manager

