

Visy Pulp and Paper Tumut CEMS - Correction Log

18/11/2025

Reporting Period: 1/10/2025 - 1/11/2025

Environment Protection Licence No: 10232

Main Stack 1

Monitoring Location No: 1
Monitoring Type: Continuous
Sample Type: Air
Description: Exit point from Stack 1 to atmosphere

Opacity		Period: 6 Minutes	Limit: 20.00 %		
Start Time	End Time	Cause	Operational State	Explanation	Max Reading
01/10/25 13:00	01/10/25 13:06	Auto Zero Span Verification	Normal (Steady State)	Auto Calibration	20.92
02/10/25 13:00	02/10/25 13:06	Auto Zero Span Verification	Normal (Steady State)	Auto Calibration	21.09
03/10/25 13:00	03/10/25 13:06	Auto Zero Span Verification	Normal (Steady State)	Auto Calibration	20.95
04/10/25 13:00	04/10/25 13:06	Auto Zero Span Verification	Normal (Steady State)	Auto Calibration	21.05
05/10/25 14:00	05/10/25 14:06	Auto Zero Span Verification	Normal (Steady State)	Auto Calibration	21.20
06/10/25 14:00	06/10/25 14:06	Auto Zero Span Verification	Normal (Steady State)	Auto Calibration	21.90
07/10/25 14:00	07/10/25 14:06	Auto Zero Span Verification	Normal (Steady State)	Auto Calibration	22.47
08/10/25 14:00	08/10/25 14:06	Auto Zero Span Verification	Normal (Steady State)	Auto Calibration	22.20
09/10/25 14:00	09/10/25 14:06	Auto Zero Span Verification	Normal (Steady State)	Auto Calibration	23.29
10/10/25 14:00	10/10/25 14:06	Auto Zero Span Verification	Normal (Steady State)	Auto Calibration	21.83
11/10/25 14:00	11/10/25 14:06	Auto Zero Span Verification	Normal (Steady State)	Auto Calibration	22.26
12/10/25 14:00	12/10/25 14:06	Auto Zero Span Verification	Normal (Steady State)	Auto Calibration	25.50
13/10/25 14:00	13/10/25 14:06	Auto Zero Span Verification	Normal (Steady State)	Auto Calibration	33.44
19/10/25 23:48	19/10/25 23:54	Instrument Error	Equipment Issue/Failure	No process plants starting, all still on MSD	30.04
20/10/25 21:00	20/10/25 21:12	Power Boiler	Power Boiler Scheduled Start-up/Shut-down	Power Boiler start up after MSD25	37.21
20/10/25 22:12	20/10/25 22:24	Auto Zero Span Verification	Normal (Steady State)	Auto Calibration	25.68

21/10/25 10:54	21/10/25 11:00	Power Boiler	Power Boiler Scheduled Start-up/Shut-down	Start firing solid fuel, initial combusting of fuel caused exceedance.	34.03
22/10/25 13:54	22/10/25 14:00	Auto Zero Span Verification	Normal (Steady State)	Auto Calibration	20.29
23/10/25 13:54	23/10/25 14:00	Auto Zero Span Verification	Normal (Steady State)	Auto Calibration	20.46
24/10/25 13:54	24/10/25 14:00	Auto Zero Span Verification	Normal (Steady State)	Auto Calibration	20.41
25/10/25 09:06	25/10/25 09:12	Auto Zero Span Verification	Normal (Steady State)	Auto Calibration	41.43
25/10/25 12:48	25/10/25 13:00	Auto Zero Span Verification	Normal (Steady State)	Auto Calibration	58.15
25/10/25 13:06	25/10/25 13:12	Auto Zero Span Verification	Normal (Steady State)	Auto Calibration	20.39
25/10/25 19:24	25/10/25 19:30	Auto Zero Span Verification	Normal (Steady State)	Auto Calibration	30.87
26/10/25 13:06	26/10/25 13:12	Auto Zero Span Verification	Normal (Steady State)	Auto Calibration	20.70
27/10/25 13:06	27/10/25 13:12	Auto Zero Span Verification	Normal (Steady State)	Auto Calibration	21.91
28/10/25 13:06	28/10/25 13:12	Auto Zero Span Verification	Normal (Steady State)	Auto Calibration	22.61
29/10/25 13:06	29/10/25 13:12	Auto Zero Span Verification	Normal (Steady State)	Auto Calibration	21.84
30/10/25 13:06	30/10/25 13:12	Auto Zero Span Verification	Normal (Steady State)	Auto Calibration	22.47
31/10/25 13:06	31/10/25 13:12	Auto Zero Span Verification	Normal (Steady State)	Auto Calibration	21.35

Power Boiler

Monitoring Location No: 3
Monitoring Type Continuous
Sample Type: Air
Description: Discharge duct downstream of Power Boiler prior to junction with Stack 1

Carbon Monoxide (CO)		Period: 60 Minutes	Limit: 140.00 mg/Nm3		
Start Time	End Time	Cause	Operational State	Explanation	Max Reading
05/10/25 21:00	05/10/25 23:00	Instrument Error	Equipment Issue/Failure	CO Probe very erratic.	351.12

Authorised By:

Uday Bhagwat
Pulp Mill Manager



Johan Stoltz
General Manager


