

Visy Pulp and Paper Tumut CEMS - Correction Log

Reporting Period: 1/08/2022 - 1/09/2022

Environment Protection Licence No: 10232

Main Stack 1

Monitoring Location No: 1
 Monitoring Type: Continuous
 Sample Type: Air
 Description: Exit point from Stack 1 to atmosphere

| Opacity | | Period: 6 Minutes | Limit: 20.00 % | | |
|----------------|----------------|-----------------------------|-----------------------|------------------|-------------|
| Start Time | End Time | Cause | Operational State | Explanation | Max Reading |
| 01/08/22 16:30 | 01/08/22 16:36 | Auto Zero Span Verification | Normal (Steady State) | Auto Calibration | 22.71 |
| 02/08/22 16:30 | 02/08/22 16:36 | Auto Zero Span Verification | Normal (Steady State) | Auto Calibration | 23.64 |
| 03/08/22 16:30 | 03/08/22 16:36 | Auto Zero Span Verification | Normal (Steady State) | Auto Calibration | 21.25 |
| 09/08/22 16:24 | 09/08/22 16:30 | Auto Zero Span Verification | Normal (Steady State) | Auto Calibration | 20.11 |
| 10/08/22 16:24 | 10/08/22 16:30 | Auto Zero Span Verification | Normal (Steady State) | Auto Calibration | 20.71 |
| 11/08/22 16:24 | 11/08/22 16:30 | Auto Zero Span Verification | Normal (Steady State) | Auto Calibration | 20.60 |
| 12/08/22 16:24 | 12/08/22 16:30 | Auto Zero Span Verification | Normal (Steady State) | Auto Calibration | 21.51 |
| 13/08/22 16:24 | 13/08/22 16:30 | Auto Zero Span Verification | Normal (Steady State) | Auto Calibration | 21.76 |
| 14/08/22 16:24 | 14/08/22 16:30 | Auto Zero Span Verification | Normal (Steady State) | Auto Calibration | 21.11 |
| 15/08/22 16:24 | 15/08/22 16:30 | Auto Zero Span Verification | Normal (Steady State) | Auto Calibration | 21.40 |
| 16/08/22 16:24 | 16/08/22 16:30 | Auto Zero Span Verification | Normal (Steady State) | Auto Calibration | 21.41 |
| 17/08/22 16:24 | 17/08/22 16:30 | Auto Zero Span Verification | Normal (Steady State) | Auto Calibration | 21.92 |
| 18/08/22 16:24 | 18/08/22 16:30 | Auto Zero Span Verification | Normal (Steady State) | Auto Calibration | 21.88 |
| 19/08/22 16:24 | 19/08/22 16:30 | Auto Zero Span Verification | Normal (Steady State) | Auto Calibration | 21.91 |
| 20/08/22 16:24 | 20/08/22 16:30 | Auto Zero Span Verification | Normal (Steady State) | Auto Calibration | 21.48 |
| 21/08/22 16:24 | 21/08/22 16:30 | Auto Zero Span Verification | Normal (Steady State) | Auto Calibration | 21.62 |
| 22/08/22 16:24 | 22/08/22 16:30 | Auto Zero Span Verification | Normal (Steady State) | Auto Calibration | 22.62 |
| 23/08/22 16:24 | 23/08/22 16:30 | Auto Zero Span Verification | Normal (Steady State) | Auto Calibration | 23.23 |

| | | | | | |
|----------------|----------------|-----------------------------|-----------------------|------------------|-------|
| 24/08/22 16:24 | 24/08/22 16:30 | Auto Zero Span Verification | Normal (Steady State) | Auto Calibration | 22.67 |
| 25/08/22 16:24 | 25/08/22 16:30 | Auto Zero Span Verification | Normal (Steady State) | Auto Calibration | 22.63 |
| 26/08/22 16:24 | 26/08/22 16:30 | Auto Zero Span Verification | Normal (Steady State) | Auto Calibration | 22.12 |

Authorised By:

Uday Bhagwat
Pulp Mill Manager



Johan Stoltz
General Manager

