

Visy Pulp and Paper Tumut CEMS - Correction Log

16/09/2020

Reporting Period: 1/08/2020 - 1/09/2020

Environment Protection Licence No: 10232

Main Stack 1

Monitoring Location No: 1

Monitoring Type: Continuous

Sample Type: Air

Description: Exit point from Stack 1 to atmosphere

Opacity					
Period: 6 Minutes		Limit: 20.00 %			
Start Time	End Time	Cause	Operational State	Explanation	Max Reading
01/08/20 14:30	01/08/20 14:36	Auto Zero Span Verification	Normal (Steady State)	Auto Calibration	22.80
02/08/20 14:30	02/08/20 14:36	Auto Zero Span Verification	Normal (Steady State)	Auto Calibration	23.01
03/08/20 14:30	03/08/20 14:36	Auto Zero Span Verification	Normal (Steady State)	Auto Calibration	21.47
04/08/20 14:30	04/08/20 14:36	Auto Zero Span Verification	Normal (Steady State)	Auto Calibration	20.68
10/08/20 14:24	10/08/20 14:30	Auto Zero Span Verification	Normal (Steady State)	Auto Calibration	20.71
11/08/20 14:24	11/08/20 14:30	Auto Zero Span Verification	Normal (Steady State)	Auto Calibration	20.75
12/08/20 14:24	12/08/20 14:30	Auto Zero Span Verification	Normal (Steady State)	Auto Calibration	21.23
13/08/20 14:24	13/08/20 14:30	Auto Zero Span Verification	Normal (Steady State)	Auto Calibration	21.10
14/08/20 14:24	14/08/20 14:30	Auto Zero Span Verification	Normal (Steady State)	Auto Calibration	21.64
15/08/20 14:24	15/08/20 14:30	Auto Zero Span Verification	Normal (Steady State)	Auto Calibration	21.49
16/08/20 14:24	16/08/20 14:30	Auto Zero Span Verification	Normal (Steady State)	Auto Calibration	21.62
17/08/20 14:24	17/08/20 14:30	Auto Zero Span Verification	Normal (Steady State)	Auto Calibration	22.20
18/08/20 14:24	18/08/20 14:30	Auto Zero Span Verification	Normal (Steady State)	Auto Calibration	22.49
19/08/20 14:24	19/08/20 14:30	Auto Zero Span Verification	Normal (Steady State)	Auto Calibration	21.96
20/08/20 14:24	20/08/20 14:30	Auto Zero Span Verification	Normal (Steady State)	Auto Calibration	21.81
21/08/20 14:24	21/08/20 14:30	Auto Zero Span Verification	Normal (Steady State)	Auto Calibration	22.61
22/08/20 14:24	22/08/20 14:30	Auto Zero Span Verification	Normal (Steady State)	Auto Calibration	22.39
23/08/20 14:24	23/08/20 14:30	Auto Zero Span Verification	Normal (Steady State)	Auto Calibration	22.92
24/08/20 14:24	24/08/20 14:30	Auto Zero Span Verification	Normal (Steady State)	Auto Calibration	23.52
25/08/20 14:24	25/08/20 14:30	Auto Zero Span Verification	Normal (Steady State)	Auto Calibration	23.76

26/08/20 14:24	26/08/20 14:30	Auto Zero Span Verification	Normal (Steady State)	Auto Calibration	22.76
27/08/20 14:24	27/08/20 14:30	Auto Zero Span Verification	Normal (Steady State)	Auto Calibration	21.45

Main Stack 2

Monitoring Location No: 22

Monitoring Type: Continuous

Sample Type: Air

Description: Exit point from Stack 2 to atmosphere

TRS (as H2S)		Period: 60 Minutes	Limit: 3.60 mg/Nm3		
Start Time	End Time	Cause	Operational State	Explanation	Max Reading
07/08/20 09:00	07/08/20 11:00	Instrument Error	Normal (Steady State)	Friday Maintenance and Calibrations	19.90
07/08/20 12:00	07/08/20 14:00	Instrument Error	Normal (Steady State)	Friday Maintenance and Calibrations	19.11
14/08/20 08:00	14/08/20 10:00	Instrument Error	Normal (Steady State)	Weekly Maintenance on CEMS	14.41
21/08/20 12:00	21/08/20 13:00	Instrument Error	Normal (Steady State)	Friday Maintenance done on CEMS	4.79
28/08/20 11:00	28/08/20 13:00	Instrument Error	Normal (Steady State)	Weekly Maintenance	12.82

Authorised By:

Uday Bhagwat
Pulp Mill Manager



Johan Stoltz
General Manager

